

Oil Field Environmental Incident Summary

Incident: 20160129192414 **Date/Time of Notice:** 01/29/2016 19:24

Responsible Party: OASIS PETROLEUM NORTH AMERICA LLC

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: DORIS H 5200 44-20B

Field Name: CAMP

Well File #: 23463

Date Incident: 1/29/2016

Time Incident: 06:30

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 100

Sec: 20

Qtr:

Location Description: HYW 29 east; 0.3 miles north on gravel road the the y intersection; go 0.8 miles west to location.

Submitted By: Dustin Anderson

Received By:

Contact Person: Dustin Anderson
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 5 Mile

Distance Nearest Water Well: 5 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.7	Barrels	0.3	Barrels	0.3	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/9/2016

Clean Up Concluded: 2/28/2016

Risk Evaluation:

Low

Areal Extent:

about 300 square feet

Potential Environmental Impacts:

slight impacts to trees and grasses

Action Taken or Planned:

Change out stuffing box gaskets when wear is noticed

Wastes Disposal Location: No disposal necessary

Agencies Involved:

Updates

Date: 2/1/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, impacted areas outside of well pad lease area. Further followup needed.

Date: 2/2/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 2/2/2016, at 1:07 p.m. Impact was to the E/SE of pad. Impacted area was pasture land and to some trees on east side of road. The pasture land impacted may be within lease area of well pad. There are booms in place to keep contaminant from traveling with snow melt water. Will need to speak with contact to get information regarding cleanup. Further follow-up is required.

Date: 5/20/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 13:56, 5/20/2016.

Minimal remaining impacts at location with the heaviest impacted vegetation on the well lease.
Request more information from company.

No on-site inspection necessary.

Date: 5/23/2016 **Status:** Correspondence

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Contact company about remaining impacts on the well lease and to the northeast of location.

More follow-up is necessary.

Date: 11/1/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 3:06, 11/1/2016.

No sign of remaining impacts off of location.

No follow-up is necessary.